

Vibrating motor G40x/GE40				
No.	Count	Designation	Туре	Standard
1	2	feather key	A8x7x12 C45K	DIN 6885
2	2	bearing cover	G4	
3	22	*) schnorr lock washer	S8	
4	8	*) hexagon socket head cap screw	M8x20	DIN7984
5	2	X centrifugal disc		
6	4	*) schnorr lock washer	S20	
7	4	*) hexagon socket head cap screw	M20x60	DIN 912
8/18	2	skala 1/ skala 2		
9	2	X centrifugal disc		
10	2	*) round cord		
11	2	X protective hood		
12	8	*) hexagon socket head cap screw	M8x14	DIN 912
13	1	screw connection	PG16	
14	1	rubber disc		
15	1	*) washer of cover of terminal box		
16	1	cover of terminal box		
17	6	*) countersunk socket screw	M8x20	DIN933
	1	**) bag for electrical circuit points		
	1	component parts fuse members G40		

X depending of type of motor; Please, contact the manufacturer for product choise under specification of serial number of the motor.

*) included in component parts fuse members

**) At delivery of the motor without connection cable a bag for electrical circuit points is included.