

Vibrating motor G32				
No.	Count	Designation	Туре	Standard
1	2	feather key	A8x7x12	DIN 6885
2	Χ	X centrifugal disc		
3/18	1	washer 1 /washer 2		
4	2	X centrifugal disc		
5	4	*) schnorr lock washer	S12	
6	4	*) hexagon socket head cap screw	M12x40	DIN 912
7	2	*) round cord		
8	2	X protective hood		
9	8	*) schnorr lock washer	S8	
10	8	*) hexagon socket head cap screw	M8x25	DIN 912
11	1	screw connection	PG16	
12	1	**) bag for electrical circuit points		
13	1	rubber disc		
14	1	*) washer of cover of terminal box		
15	1	cover of terminal box		
16	6	*) schnorr lock washer	S6	
17	6	*) hexagon socket head cap screw	M6x20	DIN 912
	1	component parts fuse members G32		

X depending of type of motor; Please, contact the manufacturer for product choise under specification of serial number of the motor.

^{*)} included in component parts fuse members

^{**)} At delivery of the motor without connection cable a bag for electrical circuit points is included.